



Maintenance Due List

18-Dec-2019

N712PR

| | | | | |
|---|----------------------------------|---------------------|------------------|------------------|
| Make & Model (Serial) BOMBARDIER CL 604 (5313) | Operator Pegasus Technologies | Date 04-Dec-2019 | Hours 7742.20 | Landings 4214 |
|---|----------------------------------|---------------------|------------------|------------------|

- Major Components

| Component | Model (Serial) | Hours | Cycles |
|-----------|-----------------------|---------|---------|
| Engine 1 | CF34-3B (872045) | 7742.20 | 4212.00 |
| Engine 2 | CF34-3B (872044) | 7742.20 | 4212.00 |
| APU 1 | GTCP36-100(E) (P-498) | 5892.00 | 3694.00 |

| ATA / Type / Group | Description | Compliance | Intervals | Tolerance | TSN/TSO | Next Due | Remaining |
|---|--|------------|--------------------------------------|-----------|---------|-------------|------------|
| AD 2017-22-02 AMD 39-19082 Airframe AD - Open FAA #3359 | IPECO HOLDINGS LTD. SEATS - TO PREVENT UNEXPECTED MOVEMENT OF PILOT AND CO-PILOT SEATS ON TAKEOFF AND LANDING (EFFECTIVE 12 DECEMBER 2017) <small>Work Order Number Scheduled</small> 712SB/AD/SL2019 01-Jan-2019 | | | | | 12-DEC-2019 | M: 0 D: -6 |
| | <small>Notes</small> INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE NOTIFY FLIGHTDOCS OF APPLICABILITY, PRIOR COMPLIANCE, AND/ OR SCHEDULING REQUIREMENTS. ALSO INCLUDE THE INSTRUCTIONS FOR THE CONTROL OF SUB PARTS. | | | | | | |
| 34 Airframe INSPECTION #3475 | ROCKWELL COLLINS NAV DATABASE UPDATE | | 04-DEC-2019 D: 28 | | | 01-JAN-2020 | M: 0 D: 14 |
| | <small>Notes</small> 28 DAYS | | | | | | |
| 27 41-00-101 Airframe INSPECTION #3091 | OPERATIONAL TEST (BITE) OF THE HORIZONTAL STABILIZER TRIM CONTROL SYSTEM (HSTCS) <small>Reference Number Work Order Number Scheduled Man Hours</small> AMM 27-41-00-740-801 INSP_DEC_2019 01-Dec-2019 0.00 | | 03-MAY-2017 H: 7362.10 L: 3958 | H: 400.00 | | H: 7762.10 | H: 19.90 |
| 28 20-00-201 APU 1 INSPECTION #596 | APU - DISCARD FUEL-FEED LINE FILTER OF THE APU <small>Reference Number Work Order Number Scheduled Man Hours</small> AMM 28 24 16 000 801 INSP_DEC_2019 01-Dec-2019 0.00 | | 13-AUG-2015 H: 5128.00 | H: 800.00 | | H: 5928.00 | H: 36.00 |
| 5 0012 Airframe INSPECTION #1 | 100 HOUR CHECK <small>Work Order Number Scheduled Man Hours</small> INSP_DEC_2019 01-Dec-2019 1.00 | | 22-JUL-2019 H: 7680.60 L: 4165 | H: 100.00 | | H: 7780.60 | H: 38.40 |
| | <small>Notes</small> COMPLETED AS PER CL-604 MM TASK 79-21-13-220-801 | | | | | | |





Maintenance Due List

N712PR

| ATA / Type / Group | Description | Compliance | Intervals | Tolerance | TSN/TSO | Next Due | Remaining |
|--|---|--------------------------------------|-----------|-----------|---------|-------------|------------|
| 57 10-00-110 Airframe INSPECTION #1313 | SPECIAL DETAILED INSPECTION OF THE LOWER WING PLANK - WS 45.00, STRINGERS 14 AND 15 Reference Number NDT ET-57-20-009 | 29-OCT-2010 H: 5027.10 L: 2905 | L: 1350 | | | L: 4255 | L: 41 |
| | Work Order Number Scheduled Man Hours INSP_DEC_ 01-Dec-2019 2019 0.00 | | | | | | |
| 57 10-00-123 Airframe INSPECTION #1320 | DETAIL INSPECTION OF LOWER WING PLANK AT REAR SPAR - WS148 Reference Number AMM 57 10 00 220 872 | 29-OCT-2010 H: 5027.10 L: 2905 | L: 1350 | | | L: 4255 | L: 41 |
| | Work Order Number Scheduled Man Hours INSP_DEC_ 01-Dec-2019 2019 0.00 | | | | | | |
| 5 0040 Airframe INSPECTION #9 | 6 MONTH CHECK | 23-JUL-2019 H: 7680.60 L: 4165 | M: 6 | | | 31-JAN-2020 | M: 1 D: 13 |
| 5 00-KCA-9016 Airframe INSPECTION #831 | BENCH CHECK EMERGENCY LIGHTING POWER SUPPLIES | 28-JAN-2019 H: 7601.10 L: 4114 | M: 12 | | | 31-JAN-2020 | M: 1 D: 13 |
| 24 30-00-202 Airframe INSPECTION #192 | FUNCTIONAL TEST MAIN BATTERY (CAPACITY CHECK) Reference Number Part Number Serial Number AMM 24 32 01 720 024637-000 090520022 801 F485 | 22-JUL-2019 H: 7680.60 L: 4165 | M: 6 | | | 31-JAN-2020 | M: 1 D: 13 |
| 24 30-00-203 Airframe INSPECTION #193 | FUNCTIONAL TEST APU BATTERY (CAPACITY CHECK) Reference Number Part Number Serial Number AMM 24 32 04 720 024453-000 0905200223 801 082 | 22-JUL-2019 H: 7680.60 L: 4165 | M: 6 | | | 31-JAN-2020 | M: 1 D: 13 |
| 33 00-KCA-9013 Airframe INSPECTION #828 | EMERGENCY LIGHTING - OPERATIONAL CHECK | 28-JAN-2019 H: 7601.10 L: 4114 | M: 12 | | | 31-JAN-2020 | M: 1 D: 13 |
| 52 45-00-301 Airframe INSPECTION #3068 | LUBRICATION OF THE SERVICE DOOR LOCKS Reference Number AMM 12-20-04-640 -837 | 18-JUL-2019 H: 7680.60 L: 4165 | M: 6 | | | 31-JAN-2020 | M: 1 D: 13 |
| 34 1201-001B Airframe INSPECTION #874 | STANDBY ALTIMETER INDICATOR 34-10-00-9502 RECERTIFY PER FAR 91.411 Part Number Serial Number 8047-10 9280B | 14-FEB-2018 H: 7440.00 L: 3992 | M: 24 | | | 14-FEB-2020 | M: 1 D: 27 |





Maintenance Due List

18-Dec-2019

N712PR

| ATA / Type / Group | Description | Compliance | Intervals | Tolerance | TSN/TSO | Next Due | Remaining |
|--|--|--------------------------------------|------------|-----------|---------|-------------|------------|
| 34 1301-001B Airframe INSPECTION #877 | RECERTIFY NO. 1 AIR DATA COMPUTER PER FAR 91.411 Part Number: 822-0842-421 Serial Number: 3115 | 14-FEB-2018 H: 7440.00 L: 3992 | M: 24 | | | 14-FEB-2020 | M: 1 D: 27 |
| 34 1301-002B Airframe INSPECTION #879 | RECERTIFY NO. 2 AIR DATA COMPUTER PER FAR 91.411 Part Number: 822-0842-421 Serial Number: 4453 | 14-FEB-2018 H: 7440.00 L: 3992 | M: 24 | | | 14-FEB-2020 | M: 1 D: 27 |
| 34 5401-001A Airframe INSPECTION #928 | RECERTIFY NO. 1 ATC TRANSPONDER PER FAR 91.413 Part Number: 622-9210-008 Serial Number: 3013 | 14-FEB-2018 H: 7440.00 L: 3992 | M: 24 | | | 14-FEB-2020 | M: 1 D: 27 |
| 34 5401-002A Airframe INSPECTION #930 | RECERTIFY NO. 2 ATC TRANSPONDER PER FAR 91.413 Part Number: 622-9210-008 Serial Number: 4497 | 14-FEB-2018 H: 7440.00 L: 3992 | M: 24 | | | 14-FEB-2020 | M: 1 D: 27 |
| SB 604-53-010 Airframe SB #2364 | SPECIAL CHECK/MODIFICATION - MIDDLE FUSELAGE - NONDESTRUCTIVE INSPECTION (NDI) CHECK AND REINFORCEMENT OF FS 484.00 BETWEEN STRINGER 15L AND STRINGER 16L EFFECTIVITY 5301 TO 5368 Notes SCHEDULED - | H: 0.00 | | | | H: 7800.00 | H: 57.80 |
| 56 10-00-102 Airframe INSPECTION #1285 | DETAILED INSPECTION OF THE SIDE WINDOW - 4 BUSHING HOLES Reference Number AMM 56 10 01 220 802 | 18-JUL-2017 H: 7416.00 L: 3978 | L: 300 | | | L: 4278 | L: 64 |
| AD 74-08-09 R3 AMD 39-16951 Airframe AD - Recurring FAA #3041 | TO PREVENT POSSIBLE FIRES THAT COULD RESULT FROM SMOKING MATERIALS BEING DROPPED INTO LAVATORY PAPER OR LINEN WASTE RECEPTACLES (REV. 3) Notes NEXT INSPECTION DUE AT 7815.1 HOURS TOTAL TIME | 13-AUG-2015 H: 6815.10 L: 3740 | H: 1000.00 | | | H: 7815.10 | H: 72.90 |
| 8 00-CUS-9001 Airframe INSPECTION 12M CK #24 | WEIGHT AND BALANCE AIRCRAFT Notes 135 operations only | 12-MAR-2019 H: 7610.30 L: 4123 | M: 12 | | | 12-MAR-2020 | M: 2 D: 23 |





Maintenance Due List

18-Dec-2019

N712PR

| ATA / Type / Group | Description | Compliance | Intervals | Tolerance | TSN/TSO | Next Due | Remaining |
|---|---|--------------------------------------|---------------------|-----------|---------|---------------------------|-------------------------|
| 57 10-00-107 Airframe INSPECTION #1310 | SPECIAL DETAILED INSPECTION OF THE LOWER WING PLANK - WS 45.00, STRINGER 10. <small>Reference Number</small> NDT ET-57-20-013 | 29-OCT-2010 H: 5027.10 L: 2905 | L: 1400 | | | L: 4305 | L: 91 |
| 24 23-00-101 Airframe INSPECTION #190 | OPERATIONAL TEST AIR DRIVEN GENERATOR (ADG). <small>Reference Number</small> AMM 24 23 01 710 801 | 26-APR-2018 H: 7448.60 L: 4002 | M: 24 H: 1600.00 | | | 26-APR-2020 H: 9048.60 | M: 4 D: 8 H: 1306.40 |
| 53 10-00-106 Airframe INSPECTION #1041 | DETAILED INSPECTION WINDSHIELD UPPER SILL - FS 234, BL2.5 <small>Reference Number</small> AMM 53 10 01 220 819 | 13-OCT-2014 H: 6453.38 L: 3595 | L: 750 | | | L: 4345 | L: 131 |
| 56 10-00-101 Airframe INSPECTION #1284 | DETAILED INSPECTION OF THE WINDSHIELD AND SIDE WINDOW LOWER T-PLATES <small>Reference Number</small> AMM 56 10 01 220 801 | 13-OCT-2014 H: 6453.38 L: 3595 | L: 750 | | | L: 4345 | L: 131 |
| 24 20-00-205 APU 1 INSPECTION 600H APU #250 | APU - DETAILED INSPECTION APU GENERATOR/ADAPTOR DRY CAVITY <small>Reference Number</small> AMM 24 22 02 220 801 | 08-DEC-2016 H: 5426.00 C: 3402 | H: 600.00 | | | H: 6026.00 | H: 134.00 |
| 49 10-00-201 APU 1 INSPECTION 600H APU #988 | APU - DETAILED INSPECTION OF THE AUXILIARY POWER UNIT (APU) ENCLOSURE ASSEMBLY. | 08-DEC-2016 H: 5426.00 C: 3402 | H: 600.00 | | | H: 6026.00 | H: 134.00 |
| 49 20-00-201 APU 1 INSPECTION 600H APU #990 | APU - INSPECT DETAILED OF THE APU COMBUSTION CHAMBER (PRE SB 604-49-006) <small>Reference Number</small> AMM 49 24 00 220 801 | 08-DEC-2016 H: 5426.00 C: 3402 | H: 600.00 | | | H: 6026.00 | H: 134.00 |
| 49 21-00-201 APU 1 INSPECTION 600H APU #992 | APU - DETAILED INSPECTION APU OIL DRAIN PLUG MAGNETIC ELEMENT (PRE SB 604-49-006) <small>Reference Number</small> AMM 49 91 22 220 801 | 08-DEC-2016 H: 5426.00 C: 3402 | H: 600.00 | | | H: 6026.00 | H: 134.00 |
| 71 10-00-102 Airframe INSPECTION #1440 | SPECIAL DETAILED INSPECTION OF THE SUPPORT FITTING OF THE NOSE COWL ACTUATOR <small>Reference Number</small> NDT ET-71-10-001 | H: 0.00 | L: 4400 | | | L: 4350 | L: 136 |





Maintenance Due List

18-Dec-2019

N712PR

| ATA / Type / Group | Description | Compliance | Intervals | Tolerance | TSN/TSO | Next Due | Remaining |
|--|--|--------------------------------------|------------|-----------|---------|-------------|------------|
| 49 20-00-205 APU 1 INSPECTION #991 | APU - VISUAL CHECK APU CONTAINMENT RING (PRE SB 604-49-006) Reference Number AMM 49-22-07-210 -802 | 10-FEB-2010 H: 3637.00 | H: 2400.00 | | | H: 6037.00 | H: 145.00 |
| 28 21-13-201 Airframe INSPECTION 600H #553 | OPERATIONAL TEST NO. 1 ENGINE FIREWALL SHUTOFF VALVE Reference Number Part Number Serial Number AMM 28 21 13 710 601-62900-8 P70607 801 | 29-MAR-2017 H: 7299.70 L: 3938 | H: 600.00 | | | H: 7899.70 | H: 157.50 |
| 28 21-13-201 Airframe INSPECTION 600H #555 | OPERATIONAL TEST NO. 2 ENGINE FIREWALL SHUTOFF VALVE Reference Number Part Number Serial Number AMM 28 21 13 710 601-62900-7 P71909 801 | 29-MAR-2017 H: 7299.70 L: 3938 | H: 600.00 | | | H: 7899.70 | H: 157.50 |
| 26 00-KCD-9036 Airframe INSPECTION #313 | GALLEY TRASH BIN EXTINGUISHER WEIGHT CHECK | 22-JUN-2017 H: 7410.40 L: 3973 | M: 36 | | | 30-JUN-2020 | M: 6 D: 12 |
| 26 00-KCD-9038 Airframe INSPECTION #315 | VANITY TRASH BIN EXTINGUISHER WEIGHT CHECK | 22-JUN-2017 H: 7410.40 L: 3973 | M: 36 | | | 30-JUN-2020 | M: 6 D: 12 |
| 35 00-00-201 Airframe INSPECTION #959 | HYDROSTATIC TEST OXYGEN CYLINDER Crew Bottle Reference Number Part Number Serial Number AMM 35 11 01 720 802895-02 ST276482 802 Notes P/N 802895-02 S/N 1920 LAST HYDRO 03/2011 | 07-JUN-2017 H: 7398.40 L: 3968 | M: 36 | | | 30-JUN-2020 | M: 6 D: 12 |
| 25 60-00-602 Airframe INSPECTION #278 | RESTORATION OF THE LIFE VESTS (IF APPLICABLE) Notes ALL VESTS EXPIRES 7/2020 | 13-AUG-2015 H: 6815.10 L: 3740 | M: 24 | | | 01-JUL-2020 | M: 6 D: 13 |
| 5 0096 Airframe INSPECTION #14 | 96 MONTH CHECK | 11-JUL-2012 H: 5696.10 L: 3304 | M: 96 | | | 11-JUL-2020 | M: 6 D: 23 |





Maintenance Due List

18-Dec-2019

N712PR

| ATA / Type / Group | Description | Compliance | Intervals | Tolerance | TSN/TSO | Next Due | Remaining |
|---|--|--------------------------------------|-----------|-----------|---------|-------------|------------|
| 32 00-01-217 Airframe INSPECTION #733 | RESTORATION (OVERHAUL) OF THE LEFT MAIN LANDING GEAR (MLG) ASSEMBLY Reference Number Part Number Serial Number AMM 32 11 00 280 604-85001-23 DCL016-96 801 | 11-JUL-2012 H: 5696.10 L: 3304 | M: 96 | | | 11-JUL-2020 | M: 6 D: 23 |
| 32 00-01-217 Airframe INSPECTION #735 | RESTORATION (OVERHAUL) OF THE RIGHT MAIN LANDING GEAR (MLG) ASSEMBLY Reference Number Part Number Serial Number AMM 32 11 00 280 604-85001-24 DCL016-96 801 | 11-JUL-2012 H: 5696.10 L: 3304 | M: 96 | | | 11-JUL-2020 | M: 6 D: 23 |
| 32 00-01-218 Airframe INSPECTION #737 | RESTORATION (OVERHAUL) OF THE NOSE LANDING GEAR (NLG) ASSEMBLY Reference Number Part Number Serial Number AMM 32 21 01 280 604-85002-1 DCL015-96 801 | 11-JUL-2012 H: 5696.10 L: 3304 | M: 96 | | | 11-JUL-2020 | M: 6 D: 23 |
| 53 10-00-218 Airframe INSPECTION #1057 | DETAILED INSPECTION OF THE AFT SIDE OF THE PILOT BULKHEAD AND FRAME - FS280.00 ABOVE WL73.50 (FLOOR LEVEL). DUE TO COMMON ACCESS, THE FOLLOWING SHOULD BE ACCOMPLISHED TOGETHER; 53-ZL-00-223, 53-10-00-218, 53-20-00-205, AND 53-30-00-205. Reference Number AMM 53-10-01-220 -828 | 11-JUL-2012 H: 5696.10 L: 3304 | M: 96 | | | 11-JUL-2020 | M: 6 D: 23 |
| 53 20-00-205 Airframe INSPECTION #1105 | DETAILED INSPECTION INTERNAL FUSELAGE (SKINS AND STRUCTURE) FS280.00 TO FS621.00 ABOVE THE FLOOR. DUE TO COMMON ACCESS, THE FOLLOWING TASKS SHOULD BE ACCOMPLISHED TOGETHER; 53-ZL-00-223, 53-10-00-218, 53-20-00-205, AND 53-30-00-205. Reference Number AMM 53 20 01 220 862 | 11-JUL-2012 H: 5696.10 L: 3304 | M: 96 | | | 11-JUL-2020 | M: 6 D: 23 |
| 53 30-00-205 Airframe INSPECTION #1163 | DETAILED INSPECTION FORWARD FACE OF THE REAR PRESSURE BULKHEAD ABOVE THE FLOOR - FS621. DUE TO COMMON ACCESS, THE FOLLOWING TASKS SHOULD BE ACCOMPLISHED TOGETHER; 53-ZL-00-223, 53-10-00-218, 53-20-00-205, AND 53-30-00-205. Reference Number AMM 53 30 01 220 805 | 11-JUL-2012 H: 5696.10 L: 3304 | M: 96 | | | 11-JUL-2020 | M: 6 D: 23 |
| 53 30-00-223 Airframe INSPECTION #1175 | SPECIAL DETAILED INSPECTION OF THE SKIN AND FUSELAGE STRUCTURE - FS718 TO FS755 Reference Number NDT ET-53-30-012 | 11-JUL-2012 H: 5696.10 L: 3304 | M: 96 | | | 11-JUL-2020 | M: 6 D: 23 |
| 53 50-00-202 Airframe INSPECTION #1179 | DETAILED INSPECTION OF THE FLOOR STRUCTURE OF THE TAIL TANK Reference Number AMM 53 66 01 220 802 | 11-JUL-2012 H: 5696.10 L: 3304 | M: 96 | | | 11-JUL-2020 | M: 6 D: 23 |





Maintenance Due List

18-Dec-2019

N712PR

| ATA / Type / Group | Description | Compliance | Intervals | Tolerance | TSN/TSO | Next Due | Remaining |
|--|---|--------------------------------------|-----------|-----------|---------|-------------|------------|
| 25 00-KCA-9104 Airframe INSPECTION #253 | GALLEY TRASH BIN DISPOSAL DOOR PROPER OPS/FIT/SEAL/LATCHING | 16-JUL-2019 H: 7678.40 L: 4164 | M: 12 | | | 16-JUL-2020 | M: 6 D: 28 |
| 25 00-KCA-9108 Airframe INSPECTION #257 | LAV TRASH BIN DISPOSAL DOORS PROPER OPERATION,FIT,SEAL,LATC | 16-JUL-2019 H: 7678.40 L: 4164 | M: 12 | | | 16-JUL-2020 | M: 6 D: 28 |
| 25 00-KCA-9114 Airframe INSPECTION #263 | CONDITION AND SECURITY OF EMERGENCY EXIT LIFE LINE MOUNT | 16-JUL-2019 H: 7678.40 L: 4164 | M: 12 | | | 16-JUL-2020 | M: 6 D: 28 |
| 25 00-KCA-9151 Airframe INSPECTION #265 | GALLEY - OPERATIONAL CHECK OPERATION OF DOORS,DRAWERS,LAT | 16-JUL-2019 H: 7678.40 L: 4164 | M: 12 | | | 16-JUL-2020 | M: 6 D: 28 |
| 26 00-KCD-9037 Airframe INSPECTION #314 | GALLEY TRASH BIN EXTINGUISHER COND. & SECURITY OF MOUNTING | 16-JUL-2019 H: 7678.40 L: 4164 | M: 12 | | | 16-JUL-2020 | M: 6 D: 28 |
| | Notes WT. 422 GRAMS 16 JUL 2019 | | | | | | |
| 26 00-KCD-9039 Airframe INSPECTION #316 | VANITY TRASH BIN EXTINGUISHER COND. & SECURITY OF MOUNTING | 16-JUL-2019 H: 7678.40 L: 4164 | M: 12 | | | 16-JUL-2020 | M: 6 D: 28 |
| | Notes WT. 420.8 GRAMS 16 JUL 2019 | | | | | | |
| 25 00-KCA-9102 Airframe INSPECTION #251 | PAX CHAIRS/DIVAN SEATBELT SEAT TRACKS - CONDITION/SECURITY | 18-JUL-2019 H: 7680.60 L: 4165 | M: 12 | | | 18-JUL-2020 | M: 7 D: 0 |
| 25 00-KCA-9110 Airframe INSPECTION #259 | CONDITION AND SECURITY OF CABINETS | 18-JUL-2019 H: 7680.60 L: 4165 | M: 12 | | | 18-JUL-2020 | M: 7 D: 0 |
| 25 00-KCA-9111 Airframe INSPECTION #260 | CONDITION AND SECURITY OF BULKHEAD MOUNTING | 18-JUL-2019 H: 7680.60 L: 4165 | M: 12 | | | 18-JUL-2020 | M: 7 D: 0 |





Maintenance Due List

18-Dec-2019

N712PR

| ATA / Type / Group | Description | Compliance | Intervals | Tolerance | TSN/TSO | Next Due | Remaining |
|--|--|--------------------------------------|-----------|-----------|---------|-------------|-----------|
| 25 00-KCA-9112 Airframe INSPECTION #261 | CONDITION AND SECURITY OF ENTERTAINMENT SYSTEM MOUNTING | 18-JUL-2019 H: 7680.60 L: 4165 | M: 12 | | | 18-JUL-2020 | M: 7 D: 0 |
| 25 00-KCA-9113 Airframe INSPECTION #262 | CONDITION AND SECURITY OF TABLE MOUNTING | 18-JUL-2019 H: 7680.60 L: 4165 | M: 12 | | | 18-JUL-2020 | M: 7 D: 0 |
| 25 00-KCA-9159 Airframe INSPECTION #266 | VANITY - OPERATIONAL CHECK OF DOORS, DRAWERS AND LATCHES | 18-JUL-2019 H: 7680.60 L: 4165 | M: 12 | | | 18-JUL-2020 | M: 7 D: 0 |
| 25 00-KCA-9163 Airframe INSPECTION #267 | CRASH AXE - VISUAL CHECK-COND & SECURITY OF MOUNTING | 18-JUL-2019 H: 7680.60 L: 4165 | M: 12 | | | 18-JUL-2020 | M: 7 D: 0 |
| 25 11-00-201 Airframe INSPECTION 36M CK #271 | OPERATIONAL TEST OF THE INERTIAL REEL CONTROL AND INERTIAL REEL Reference Number AMM 25 11 04 710 801 | 18-JUL-2017 H: 7416.00 L: 3978 | M: 36 | | | 18-JUL-2020 | M: 7 D: 0 |
| 25 11-00-202 Airframe INSPECTION 36M CK #272 | INSPECT GENERAL VISUAL INSPECTION GENERAL VISUAL OF PILOT/COPILOT SEAT RESTRAINTS Reference Number AMM 25 11 01 210 801 | 18-JUL-2017 H: 7416.00 L: 3978 | M: 36 | | | 18-JUL-2020 | M: 7 D: 0 |
| 27 00-00-210 Airframe INSPECTION 36M CK #361 | DETAILED INSPECTION OF THE AILERON CONTROL CABLES IN THE INBOARD TRAILING EDGE Reference Number AMM 27 11 00 220 812 | 18-JUL-2017 H: 7416.00 L: 3978 | M: 36 | | | 18-JUL-2020 | M: 7 D: 0 |
| 27 00-00-211 Airframe INSPECTION 36M CK #362 | DETAILED INSPECTION OF THE AILERON CONTROL CABLES IN THE OUTBOARD TRAILING EDGE Reference Number AMM 27 11 00 220 813 | 18-JUL-2017 H: 7416.00 L: 3978 | M: 36 | | | 18-JUL-2020 | M: 7 D: 0 |
| 35 00-00-204 Airframe INSPECTION 36M CK #942 | OPERATIONAL TEST CREW OXYGEN MASK Reference Number AMM 35 11 07 710 801 | 18-JUL-2017 H: 7416.00 L: 3978 | M: 36 | | | 18-JUL-2020 | M: 7 D: 0 |





Maintenance Due List

18-Dec-2019

N712PR

| ATA / Type / Group | Description | Compliance | Intervals | Tolerance | TSN/TSO | Next Due | Remaining |
|---|---|--------------------------------------|-----------|-----------|---------|-------------|-----------|
| 52 20-00-201 Airframe INSPECTION 36M CK #1018 | OPERATIONAL TEST OF LATCH MECHANISM OF O/WING EMERGENCY EXIT DOOR <small>Reference Number</small> AMM 52 21 04 710 801 | 18-JUL-2017 H: 7416.00 L: 3978 | M: 36 | | | 18-JUL-2020 | M: 7 D: 0 |
| 57 ZL-00-228 Airframe INSPECTION 36M CK #1423 | GENERAL VISUAL INSPECTION WING TRAILING EDGE - INTERNAL LH <small>Reference Number</small> AMM 57 50 01 210 802 | 18-JUL-2017 H: 7416.00 L: 3978 | M: 36 | | | 18-JUL-2020 | M: 7 D: 0 |
| 57 ZL-00-229 Airframe INSPECTION 36M CK #1424 | GENERAL VISUAL INSPECTION WING TRAILING EDGE - INTERNAL RH <small>Reference Number</small> AMM 57 50 01 210 802 | 18-JUL-2017 H: 7416.00 L: 3978 | M: 36 | | | 18-JUL-2020 | M: 7 D: 0 |
| 71 ZL-00-203 Airframe INSPECTION 36M CK #1463 | GENERAL VISUAL INSPECTION NOSE INLET ACCESS COWL - INSIDE LH <small>Reference Number</small> AMM 71 61 01 210 803 | 18-JUL-2017 H: 7416.00 L: 3978 | M: 36 | | | 18-JUL-2020 | M: 7 D: 0 |
| 71 ZL-00-204 Airframe INSPECTION 36M CK #1464 | GENERAL VISUAL INSPECTION NOSE INLET ACCESS COWL - INSIDE RH <small>Reference Number</small> AMM 71 61 01 210 803 | 18-JUL-2017 H: 7416.00 L: 3978 | M: 36 | | | 18-JUL-2020 | M: 7 D: 0 |
| 71 ZL-00-207 Airframe INSPECTION 36M CK #1467 | GENERAL VISUAL INSPECTION OF THE CORE COWL - INTERNAL LH <small>Reference Number</small> AMM 71 12 01 210 805 | 18-JUL-2017 H: 7416.00 L: 3978 | M: 36 | | | 18-JUL-2020 | M: 7 D: 0 |
| 71 ZL-00-208 Airframe INSPECTION 36M CK #1468 | GENERAL VISUAL INSPECTION OF THE CORE COWL - INTERNAL RH <small>Reference Number</small> AMM 71 12 01 210 805 | 18-JUL-2017 H: 7416.00 L: 3978 | M: 36 | | | 18-JUL-2020 | M: 7 D: 0 |
| 25 00-KCA-9103 Airframe INSPECTION #252 | CONDITION & SECURITY OF GALLEY MOUNTING | 19-JUL-2019 H: 7680.60 L: 4165 | M: 12 | | | 19-JUL-2020 | M: 7 D: 1 |
| 25 00-KCA-9168 Airframe INSPECTION #269 | FWD CLOSETS, INS FOR CONDITION AND SECURITY OF MOUNTING LH/RH | 19-JUL-2019 H: 7680.60 L: 4165 | M: 12 | | | 19-JUL-2020 | M: 7 D: 1 |





Maintenance Due List

N712PR

| ATA / Type / Group | Description | Compliance | Intervals | Tolerance | TSN/TSO | Next Due | Remaining |
|--|--|--------------------------------------|--------------------|-----------|---------|---------------------------|------------------------|
| 25 00-KCA-9169 Airframe INSPECTION #270 | FWD CLOSETS OPERATIONAL CHECK OF DOORS DRAWERS LATCHES LH/RH | 19-JUL-2019 H: 7680.60 L: 4165 | M: 12 | | | 19-JUL-2020 | M: 7 D: 1 |
| 30 40-00-301 Airframe INSPECTION #3135 | DETAILED INSPECTION OF THE WINDSHIELD/SIDE WINDOW AERODYNAMIC SEAL Reference Number AMM 56-10-01-220 -804 | 19-JUL-2019 H: 7680.60 L: 4165 | M: 12 H: 600.00 | | | 19-JUL-2020 H: 8280.60 | M: 7 D: 1 H: 538.40 |
| 25 00-KCA-9107 Airframe INSPECTION #256 | CONDITION & SECURITY OF TOILET /VANITY MOUNTING | 22-JUL-2019 H: 7680.60 L: 4165 | M: 12 | | | 22-JUL-2020 | M: 7 D: 4 |
| 25 00-KCA-9116 Airframe INSPECTION #264 | TOILET AREA - CHECK FOR CORROSION AND LEAKAGE | 22-JUL-2019 H: 7680.60 L: 4165 | M: 12 | | | 22-JUL-2020 | M: 7 D: 4 |
| 11 00-KCA-9004 Airframe INSPECTION #25 | REQUIRED PLACARDS - IN PLACE & LEGIBLE | 23-JUL-2019 H: 7680.60 L: 4165 | M: 12 | | | 23-JUL-2020 | M: 7 D: 5 |
| 25 00-KCA-9167 Airframe INSPECTION #268 | MAGNASTAR RAD/TEL SYS-VIS CK COND & SECURITY OF MOUNTING | 23-JUL-2019 H: 7680.60 L: 4165 | M: 12 | | | 23-JUL-2020 | M: 7 D: 5 |
| 38 00-KCA-9020 Airframe INSPECTION #980 | CONDITION AND SECURITY OF WATER SUPPLY MOUNTING | 23-JUL-2019 H: 7680.60 L: 4165 | M: 12 | | | 23-JUL-2020 | M: 7 D: 5 |
| 38 00-KCA-9021 Airframe INSPECTION #981 | CONDITION & SECURITY OF SONIC DRAIN MASTS MOUNTING | 23-JUL-2019 H: 7680.60 L: 4165 | M: 12 | | | 23-JUL-2020 | M: 7 D: 5 |
| | Notes COOMPLETED BY DONNIE FERRY AP310919 | | | | | | |
| 38 00-KCA-9032 Airframe INSPECTION #982 | DRAIN MAST - VISUAL CHECK FOR CONDITION & SECURITY OF MOUNTG | 23-JUL-2019 H: 7680.60 L: 4165 | M: 12 | | | 23-JUL-2020 | M: 7 D: 5 |
| | Notes COMPLETED BY MATT SCRIMO AP3251235. | | | | | | |





Maintenance Due List

N712PR

| ATA / Type / Group | Description | Compliance | Intervals | Tolerance | TSN/TSO | Next Due | Remaining |
|---|--|--------------------------------------|-----------|-----------|---------|-------------|------------|
| 26 00-KCA-9024 Airframe INSPECTION #307 | SMOKE DETECTORS - OPERATIONAL TEST | 25-JUL-2019 H: 7680.60 L: 4165 | M: 12 | | | 25-JUL-2020 | M: 7 D: 7 |
| 5 0042 Airframe INSPECTION #10 | 12 MONTH CHECK | 23-JUL-2019 H: 7680.60 L: 4165 | M: 12 | | | 31-JUL-2020 | M: 7 D: 13 |
| 5 0046 Airframe INSPECTION #12 | 36 MONTH CHECK | 18-JUL-2017 H: 7416.00 L: 3978 | M: 36 | | | 31-JUL-2020 | M: 7 D: 13 |
| 25 00-KCA-9109 Airframe INSPECTION #258 | FIRST AID KIT - CHECK FOR COMPLETENESS | 16-JUL-2019 H: 7678.40 L: 4164 | M: 12 | | | 31-JUL-2020 | M: 7 D: 13 |
| 25 00-KCA-9250 Airframe INSPECTION #3027 | Interior Doors Condition and Security of Mounting and Latches | 19-JUL-2019 H: 7680.60 L: 4165 | M: 12 | | | 31-JUL-2020 | M: 7 D: 13 |
| 25 60-00-201 Airframe INSPECTION #303 | OPERATIONAL TEST (ELT) EMERGENCY LOCATOR TRANSMITTER Reference Number Part Number Serial Number AMM 25 62 00 710 95210000-21 0214 801 | 22-JUL-2019 H: 7680.60 L: 4165 | M: 12 | | | 31-JUL-2020 | M: 7 D: 13 |
| 25 60-00-203 Airframe INSPECTION #276 | DETAILED INSPECTION EMERGENCY LOCATOR TRANSMITTER (ELT) BATTERY Reference Number Part Number Serial Number AMM 25 62 01 220 95210000-21 0214 801 Notes BATTERY EXP DATE 10/1/2019 | 22-JUL-2019 H: 7680.60 L: 4165 | M: 12 | | | 31-JUL-2020 | M: 7 D: 13 |
| 25 60-00-601 Airframe INSPECTION #277 | INSPECT DETAILED OF LIFE VESTS EXPIRATION DATE Notes NEXT EXPIRATION DATE 07/2020 (ALL VESTS) | 13-AUG-2015 H: 6815.10 L: 3740 | M: 12 | | | 31-JUL-2020 | M: 7 D: 13 |





Maintenance Due List

18-Dec-2019

N712PR

| ATA / Type / Group | Description | Compliance | Intervals | Tolerance | TSN/TSO | Next Due | Remaining |
|---|---|--------------------------------------|-----------|-----------|---------|-------------|------------|
| 25 60-00-602 Airframe PART #3234 | LIFE VEST #1 Part Number 0723E105PW Serial Number 44028 | 13-AUG-2015 H: 6815.10 L: 3740 | | | | 31-JUL-2020 | M: 7 D: 13 |
| | Notes EXP DATE 07/2020 | | | | | | |
| 25 60-00-602 Airframe PART #3225 | LIFE VEST #10 Part Number 0723E105PW Serial Number 44073 | 13-AUG-2015 H: 6815.10 L: 3740 | | | | 31-JUL-2020 | M: 7 D: 13 |
| | Notes EXP 07/2020 | | | | | | |
| 25 60-00-602 Airframe PART #3224 | LIFE VEST #11 Part Number 0723E105PWC Serial Number 69375 | 13-AUG-2015 H: 6815.10 L: 3740 | | | | 31-JUL-2020 | M: 7 D: 13 |
| | Notes EXP 07/2020 | | | | | | |
| 25 60-00-602 Airframe PART #3223 | LIFE VEST #12 Part Number 0723E105PWC Serial Number 44264 | 13-AUG-2015 H: 6815.10 L: 3740 | | | | 31-JUL-2020 | M: 7 D: 13 |
| | Notes EXP: 07/2020 | | | | | | |
| 25 60-00-602 Airframe PART #3233 | LIFE VEST #2 Part Number 0723E105PW Serial Number 40933 | 13-AUG-2015 H: 6815.10 L: 3740 | | | | 31-JUL-2020 | M: 7 D: 13 |
| | Notes EXP DATE 07/2020 | | | | | | |
| 25 60-00-602 Airframe PART #3232 | LIFE VEST #3 Part Number 0723E105PW Serial Number 44026 | 13-AUG-2015 H: 6815.10 L: 3740 | | | | 31-JUL-2020 | M: 7 D: 13 |
| | Notes EXP DATE 07/2020 | | | | | | |





Maintenance Due List

18-Dec-2019

N712PR

| ATA / Type / Group | Description | Compliance | Intervals | Tolerance | TSN/TSO | Next Due | Remaining |
|--|---|--------------------------------------|-----------|-----------|---------|-------------|------------|
| 25 60-00-602 Airframe PART #3231 | LIFE VEST #4 Part Number 0723E105PW Serial Number 40905 | 13-AUG-2015 H: 6815.10 L: 3740 | | | | 31-JUL-2020 | M: 7 D: 13 |
| | Notes EXP DATE 07/2020 | | | | | | |
| 25 60-00-602 Airframe PART #3230 | LIFE VEST #5 Part Number 0723E105PW Serial Number 44037 | 13-AUG-2015 H: 6815.10 L: 3740 | | | | 31-JUL-2020 | M: 7 D: 13 |
| | Notes EXP DATE 07/2020 | | | | | | |
| 25 60-00-602 Airframe PART #3229 | LIFE VEST #6 Part Number 0723E105PW Serial Number 40900 | 13-AUG-2015 H: 6815.10 L: 3740 | | | | 31-JUL-2020 | M: 7 D: 13 |
| | Notes EXP : 07/2020 | | | | | | |
| 25 60-00-602 Airframe PART #3228 | LIFE VEST #7 Part Number 0723E105PW Serial Number 40914 | 13-AUG-2015 H: 6815.10 L: 3740 | | | | 31-JUL-2020 | M: 7 D: 13 |
| | Notes EXP DATE: 07/2020 | | | | | | |
| 25 60-00-602 Airframe PART #3227 | LIFE VEST #8 Part Number 0723E105PW Serial Number 44059 | 13-AUG-2015 H: 6815.10 L: 3740 | | | | 31-JUL-2020 | M: 7 D: 13 |
| | Notes EXP DATE: 07/2020 | | | | | | |
| 25 60-00-602 Airframe PART #3226 | LIFE VEST #9 Part Number 0723E105PW Serial Number 44011 | 13-AUG-2015 H: 6815.10 L: 3740 | | | | 31-JUL-2020 | M: 7 D: 13 |
| | Notes EXP DATE: 07/2020 | | | | | | |
| 33 00-KCA-9014 Airframe INSPECTION #829 | CABIN LIGHTING - OPERATIONAL CHECK | 22-JUL-2019 H: 7680.60 L: 4165 | M: 12 | | | 31-JUL-2020 | M: 7 D: 13 |





Maintenance Due List

18-Dec-2019

N712PR

| ATA / Type / Group | Description | Compliance | Intervals | Tolerance | TSN/TSO | Next Due | Remaining |
|---|--|--------------------------------------|-----------|-----------|---------|-------------|------------|
| 35 00-KCA-9056 Airframe INSPECTION #951 | PORTABLE OXYGEN BOTTLE- VISUAL CHECK COND & SECURITY OF MOUNT | 17-JUL-2019 H: 7678.40 L: 4164 | M: 12 | | | 31-JUL-2020 | M: 7 D: 13 |
| 27 35-04-101 Airframe INSPECTION LEFT AOA #442 | FUNCTIONAL TEST NO. 1 ANGLE OF ATTACK TRANSDUCER LINEARITY Reference Number Part Number Serial Number AMM 27 35 04 720 600-59154-3 GST04092 801 | 22-JUL-2019 H: 7680.60 L: 4165 | H: 300.00 | | | H: 7980.60 | H: 238.40 |
| 27 35-04-101 Airframe INSPECTION RIGHT AOA #445 | FUNCTIONAL TEST NO. 2 ANGLE OF ATTACK TRANSDUCER LINEARITY Reference Number Part Number Serial Number AMM 27 35 04 720 600-59154-3 GST02387 801 | 22-JUL-2019 H: 7680.60 L: 4165 | H: 300.00 | | | H: 7980.60 | H: 238.40 |
| 32 00-01-204 Airframe INSPECTION #682 | LUBRICATION OF MAIN LANDING GEAR Reference Number AMM 12 20 04 640 802 | 18-JUL-2019 H: 7680.60 L: 4165 | H: 300.00 | | | H: 7980.60 | H: 238.40 |
| 32 00-01-205 Airframe INSPECTION #683 | LUBRICATION OF THE NOSE LANDING GEAR Reference Number AMM 12 20 04 640 801 | 18-JUL-2019 H: 7680.60 L: 4165 | H: 300.00 | | | H: 7980.60 | H: 238.40 |
| 32 00-01-206 Airframe INSPECTION #684 | LUBRICATION MAIN LANDING GEAR (MLG) DOORS Reference Number AMM 12 20 04 640 833 | 18-JUL-2019 H: 7680.60 L: 4165 | H: 300.00 | | | H: 7980.60 | H: 238.40 |
| 32 00-01-207 Airframe INSPECTION #685 | LUBRICATION NOSE LANDING GEAR (NLG) DOORS Reference Number AMM 12 20 04 640 832 | 18-JUL-2019 H: 7680.60 L: 4165 | H: 300.00 | | | H: 7980.60 | H: 238.40 |
| 52 10-00-202 Airframe INSPECTION #1010 | LUBRICATION THE PASSENGER DOOR (EXTERNAL) Reference Number AMM 12 20 04 640 807 | 18-JUL-2019 H: 7680.60 L: 4165 | H: 300.00 | | | H: 7980.60 | H: 238.40 |





Maintenance Due List

N712PR

| ATA / Type / Group | Description | Compliance | Intervals | Tolerance | TSN/TSO | Next Due | Remaining |
|---|---|--------------------------------------|-----------|-----------|---------|-------------|------------|
| AD 2003-22-12 PARA H LEFT Airframe AD - Recurring FAA #1811 | SPECIAL CHECK/REWORK - STALL PROTECTION SYSTEM - LEFT ANGLE-OF-ATTACK (AOA) TRANSDUCER TOLERANCE CHECK AND REWORK OF OUT-OF-TOLERANCE AOA TRANSDUCER ASSEMBLIES (TASK 27-35-04-101*) | 22-JUL-2019 H: 7680.60 L: 4165 | H: 300.00 | | | H: 7980.60 | H: 238.40 |
| | Notes COMPLIED WITH | | | | | | |
| AD 2003-22-12 PARA H RIGHT Airframe AD - Recurring FAA #1812 | SPECIAL CHECK/REWORK - STALL PROTECTION SYSTEM - RIGHT ANGLE-OF-ATTACK (AOA) TRANSDUCER TOLERANCE CHECK AND REWORK OF OUT-OF-TOLERANCE AOA TRANSDUCER ASSEMBLIES (AND TASK 27-35-04-101*) | 22-JUL-2019 H: 7680.60 L: 4165 | H: 300.00 | | | H: 7980.60 | H: 238.40 |
| | Notes COMPLIED WITH | | | | | | |
| 35 00-00-210 Airframe INSPECTION #2999 | RESTORATION OF THE OXYGEN CYLINDER REGULATOR. Reference Number 35-11-01-280-801 | 13-AUG-2015 H: 6815.10 L: 3740 | M: 60 | | | 13-AUG-2020 | M: 7 D: 26 |
| 35 3001-701A Airframe INSPECTION #962 | CAB PORTABLE OXYGEN PASSENGER BOTTLE CAB 35-00-04-9001 HYDRO TEST PORTABLE OXY CYL Part Number 894-20330 Serial Number 026113 | 13-AUG-2015 H: 6815.10 L: 3740 | M: 60 | | | 13-AUG-2020 | M: 7 D: 26 |
| 26 21-04-201 Airframe INSPECTION #331 | DETAILED INSPECTION NO. 1 FIRE EXTINGUISHER ENGINE BOTTLE PRESSURE GAUGE Reference Number AMM 26 21 04 220 Part Number 601-65910-9 Serial Number 15504EL 802 | 23-AUG-2018 H: 7516.80 L: 4050 | M: 24 | | | 23-AUG-2020 | M: 8 D: 5 |
| 26 21-04-201 Airframe INSPECTION #334 | DETAILED INSPECTION NO. 2 FIRE EXTINGUISHER ENGINE BOTTLE PRESSURE GAUGE Reference Number AMM 26 21 04 220 Part Number 601-65910-9 Serial Number 15510EL 802 | 23-AUG-2018 H: 7516.80 L: 4050 | M: 24 | | | 23-AUG-2020 | M: 8 D: 5 |
| 26 22-04-201 Airframe INSPECTION #337 | DETAILED INSPECTION APU FIRE EXTINGUISHER BOTTLE PRESSURE GAUGE Reference Number AMM 26 22 04 220 Part Number 600-65904-3 Serial Number 15815EL 802 | 23-AUG-2018 H: 7516.80 L: 4050 | M: 24 | | | 23-AUG-2020 | M: 8 D: 5 |
| 35 00-KCA-9036 Airframe INSPECTION #943 | PAX OXYGEN CYLINDER ASSEMBLY CONDITION, SECURITY & MOUNTING | 23-AUG-2018 H: 7516.80 L: 4050 | M: 24 | | | 23-AUG-2020 | M: 8 D: 5 |





Maintenance Due List

N712PR

| ATA / Type / Group | Description | Compliance | Intervals | Tolerance | TSN/TSO | Next Due | Remaining |
|--|---|--------------------------------------|-----------|-----------|---------|-------------|-----------|
| 35 00-KCA-9038 Airframe INSPECTION #945 | EROS MASK-CONDITION,SECURITY & MOUNTING OF OXYGEN MASK BOX | 23-AUG-2018 H: 7516.80 L: 4050 | M: 24 | | | 23-AUG-2020 | M: 8 D: 5 |
| 5 0048 Airframe INSPECTION #13 | 48 MONTH CHECK | 24-AUG-2016 H: 7077.90 L: 3851 | M: 48 | | | 24-AUG-2020 | M: 8 D: 6 |
| 23 60-00-202 Airframe INSPECTION #2990 | FUNCTIONAL TEST (BONDING CHECK) OF THE STATIC DISCHARGER BASE. Reference Number AMM 23-61-04-720 -801 | 24-AUG-2016 H: 7077.90 L: 3851 | M: 48 | | | 24-AUG-2020 | M: 8 D: 6 |
| 32 10-00-201 Airframe INSPECTION #2998 | SPECIAL DETAILED INSPECTION OF THE MAIN LANDING-GEAR SIDE BRACE FITTING SHAFT, PART NO. 601R10237-1 ONLY Reference Number NDT MT-32-10-001 | 24-AUG-2016 H: 7077.90 L: 3851 | M: 48 | | | 24-AUG-2020 | M: 8 D: 6 |
| 35 00-KCA-9040 Airframe INSPECTION #947 | PAX MASKS-CONDITION,SECURITY & MOUNTG OF 02 MASK PRESENTN BOX | 24-AUG-2018 H: 7516.80 L: 4050 | M: 24 | | | 24-AUG-2020 | M: 8 D: 6 |
| 35 00-KCA-9041 Airframe INSPECTION #948 | PAX MASKS - OPERATIONAL CHECK (FLOW CHECK) | 24-AUG-2018 H: 7518.60 L: 4050 | M: 24 | | | 24-AUG-2020 | M: 8 D: 6 |
| 35 00-KCA-9042 Airframe INSPECTION #949 | THERAPEUTIC OUTLET - CONDITION SECURITY & MOUNTING OF OUTLET | 24-AUG-2018 H: 7516.80 L: 4050 | M: 24 | | | 24-AUG-2020 | M: 8 D: 6 |
| 35 00-KCA-9043 Airframe INSPECTION #950 | THERAPEUTIC OUTLET-OPERATIONAL CHECK (FLOW CHECK) | 24-AUG-2018 H: 7516.80 L: 4050 | M: 24 | | | 24-AUG-2020 | M: 8 D: 6 |
| 35 00-KCA-9057 Airframe INSPECTION #952 | DEPLOYMENT CONTAINERS-VIS CK FOR CONDITION AND MOUNTING | 24-AUG-2018 H: 7516.80 L: 4050 | M: 24 | | | 24-AUG-2020 | M: 8 D: 6 |





Maintenance Due List

N712PR

| ATA / Type / Group | Description | Compliance | Intervals | Tolerance | TSN/TSO | Next Due | Remaining |
|---|---|--------------------------------------|------------|-----------|---------|-------------|------------|
| 53 10-00-204 Airframe INSPECTION #1052 | DETAILED INSPECTION OF THE INTERNAL FUSELAGE, SKIN AND STRUCTURE - FS202.75 TO FS280.00 ABOVE THE FLOOR. Reference Number AMM 53 10 01 220 804 | 24-AUG-2016 H: 7077.90 L: 3851 | M: 48 | | | 24-AUG-2020 | M: 8 D: 6 |
| 53 20-00-233 Airframe INSPECTION #1126 | LUBRICATION OF THE WING -TO-FUSELAGE ATTACHMENT LINKS - FS513.00 Reference Number AMM 12 20 04 640 819 | 24-AUG-2016 H: 7077.90 L: 3851 | M: 48 | | | 24-AUG-2020 | M: 8 D: 6 |
| 35 00-KCA-9037 Airframe INSPECTION #944 | PAX OXYGEN CYLINDER ASSEMBLY - HYDROSTATIC TEST OF CYLINDERS Part Number 894-20330 Serial Number 026113 | 13-AUG-2015 H: 6815.10 L: 3740 | M: 36 | | | 30-AUG-2020 | M: 8 D: 12 |
| | Notes NEXT TEST DUE 08/2020 | | | | | | |
| 5 0044 Airframe INSPECTION #11 | 24 MONTH CHECK | 10-SEP-2018 H: 7518.60 L: 4050 | M: 24 | | | 10-SEP-2020 | M: 8 D: 23 |
| 72 1001 Engine 1 INSPECTION #3356 | ENGINE AND FAN ROTOR WATER WASH Reference Number GE SEI 72-00-00 | 21-MAR-2019 H: 7610.30 C: 4123 | H: 400.00 | | | H: 8010.30 | H: 268.10 |
| 72 1002 Engine 2 INSPECTION #3357 | ENGINE AND FAN ROTOR WATER WASH Reference Number GE SEI 72-00-00 | 21-MAR-2019 H: 7610.30 C: 4123 | H: 400.00 | | | H: 8010.30 | H: 268.10 |
| 21 20-00-202 Airframe INSPECTION 1200H #27 | OPERATIONAL TEST AVIONICS EXHAUST FAN LOW SPEED DETECTOR Reference Number AMM 21 24 22 710 801 Part Number 604-96001-1 Serial Number C98381489 | 13-AUG-2015 H: 6815.10 L: 3740 | H: 1200.00 | | | H: 8015.10 | H: 272.90 |
| 24 30-00-204 Airframe INSPECTION 1200H #194 | OPERATIONAL TEST DC ESSENTIAL BUS Reference Number AMM 24 61 00 710 803 | 13-AUG-2015 H: 6815.10 L: 3740 | H: 1200.00 | | | H: 8015.10 | H: 272.90 |





Maintenance Due List

N712PR

| ATA / Type / Group | Description | Compliance | Intervals | Tolerance | TSN/TSO | Next Due | Remaining |
|---|--|--------------------------------------|------------|-----------|---------|------------|-----------|
| 24 30-00-206 Airframe INSPECTION 1200H #196 | OPERATIONAL TEST DC EMERGENCY BUS Reference Number AMM 24 61 00 710 802 | 13-AUG-2015 H: 6815.10 L: 3740 | H: 1200.00 | | | H: 8015.10 | H: 272.90 |
| 27 50-00-201 Airframe INSPECTION 1200H #389 | FUNCTIONAL TEST ASYMMETRY/OVERSPEED DETECTOR AND BRAKE UNIT Reference Number AMM 27 51 07 720 801 | 13-AUG-2015 H: 6815.10 L: 3740 | H: 1200.00 | | | H: 8015.10 | H: 272.90 |
| 30 81-00-201 Airframe INSPECTION 1200H #643 | OPERATIONAL TEST ICE DETECTION SYSTEM Reference Number Part Number Serial Number AMM 30 81 00 710 871BN3-8 3666 801 | 13-AUG-2015 H: 6815.10 L: 3740 | H: 1200.00 | | | H: 8015.10 | H: 272.90 |
| 5 0015 Airframe INSPECTION #3136 | 600 HOUR CHECK | 18-JUL-2017 H: 7416.00 L: 3978 | H: 600.00 | | | H: 8016.00 | H: 273.80 |
| 79 00-00-203 Engine 1 INSPECTION #1755 | NO. 1 ENGINE - VISUAL CHECK OIL FILTER IMPENDING BYPASS INDICATOR Reference Number AMM 79 30 10 210 801 | 18-JUL-2017 H: 7416.00 C: 4038 | H: 600.00 | H: 40.00 | | H: 8016.00 | H: 273.80 |
| 79 00-00-203 Engine 2 INSPECTION #1766 | NO. 2 ENGINE - VISUAL CHECK OIL FILTER IMPENDING BYPASS INDICATOR Reference Number AMM 79 30 10 210 801 | 18-JUL-2017 H: 7416.00 C: 4038 | H: 600.00 | H: 40.00 | | H: 8016.00 | H: 273.80 |
| 57 10-00-153 Airframe INSPECTION #3046 | DETAILED INSPECTION OF THE LOWER WING PLANK - WS88.0 Reference Number AMM 57-10-00-220 -874 | 13-AUG-2015 H: 6815.10 L: 3740 | L: 750 | | | L: 4490 | L: 276 |
| 49 30-00-201 APU 1 INSPECTION #993 | APU - DISCARD APU FUEL FILTER ELEMENT (PRE SB 604-49-006) Reference Number AMM 49 31 01 960 801 | 29-JAN-2019 H: 5775.00 C: 3591 | H: 400.00 | | | H: 6175.00 | H: 283.00 |





Maintenance Due List

N712PR

| ATA / Type / Group | Description | Compliance | Intervals | Tolerance | TSN/TSO | Next Due | Remaining |
|--|---|--------------------------------------|------------|-----------|---------|-------------|------------|
| 49 90-00-201 APU 1 INSPECTION #998 | APU - DISCARD APU OIL FILTER ELEMENT (PRE SB 604-49-006) Reference Number AMM 49 91 07 960 804 Notes NOTE:SOAP TESTING MAY BE USED IN LIEU OF THIS TASK. REFER TO HONEYWELL SIL NO.;;APU-49 REV 8 OR LATEST REV. | 29-JAN-2019 H: 5775.00 C: 3591 | H: 400.00 | | | H: 6175.00 | H: 283.00 |
| 25 00-KCA-9106 Airframe INSPECTION #255 | LIFE RAFTS-INFLATE & LEAK CHCK RET TO MANUF OR APPRV FACILITY Notes NOT DUE UNTIL 10/2017 | 11-SEP-2018 H: 7518.60 L: 4050 | M: 24 | | | 30-SEP-2020 | M: 9 D: 12 |
| 34 003 Airframe PART - Expiration #3434 | FMC Card #3 P/N: 822-0868-029 S/N: YYTF due for battery replacement at Rockwell Collins. Part Number 822-0868-029 Serial Number YYTF | 03-JUL-2018 | | | | 01-OCT-2020 | M: 9 D: 13 |
| 5 0023 Airframe INSPECTION #4 | 1600 HOUR CHECK | 13-OCT-2014 H: 6453.38 L: 3595 | H: 1600.00 | | | H: 8053.38 | H: 311.18 |
| 24 21-00-101 Airframe INSPECTION #189 | FUNCTIONAL TEST GCU OVERVOLTAGE PROTECTION CIRCUITS Reference Number AMM 24 20 00 720 801 | 13-OCT-2014 H: 6453.38 L: 3595 | H: 1600.00 | | | H: 8053.38 | H: 311.18 |
| 27 31-13-102 Airframe INSPECTION #422 | FUNCTIONAL TEST OF THE NO. 1 PITCH FEEL SIMULATOR Reference Number AMM 27 31 13 720 801 Part Number 600-92300-61 Serial Number 10552 | 13-OCT-2014 H: 6453.38 L: 3595 | H: 1600.00 | | | H: 8053.38 | H: 311.18 |
| 27 31-13-102 Airframe INSPECTION #424 | FUNCTIONAL TEST OF THE NO. 2 PITCH FEEL SIMULATOR Reference Number AMM 27 31 13 720 801 Part Number 600-92300-61 Serial Number 10553 | 13-OCT-2014 H: 6453.38 L: 3595 | H: 1600.00 | | | H: 8053.38 | H: 311.18 |
| 5 0013 Airframe INSPECTION #2 | 400 HOUR CHECK | 24-JUL-2019 H: 7680.60 L: 4165 | H: 400.00 | | | H: 8080.60 | H: 338.40 |





Maintenance Due List

N712PR

| ATA / Type / Group | Description | Compliance | Intervals | Tolerance | TSN/TSO | Next Due | Remaining |
|--|---|--------------------------------------|-----------|-----------|---------|-------------|-------------|
| 25 60-00-603 Airframe INSPECTION #279 | INSPECT DETAILED OF LIFE RAFTS EXPIRATION DATE Reference Number AMM 27-35-04-720 -801 Notes CO2 BOTTLE HYDRO: 10/2020 ELT BATTERY: 06/2022 NEXT SERVICE DUE: 09/2019 | 06-NOV-2019 H: 7728.10 L: 4199 | M: 12 | | | 30-NOV-2020 | M: 11 D: 12 |
| 31 31-00-201 Airframe INSPECTION #668 | DISCARD FDR (ULB) UNDERWATER LOCATOR BEACON BATTERY Reference Number Part Number Serial Number AMM 31 31 07 960 266-E0305-00 SD50270 801 Notes NEXT EXPIRE DATE: 12/2020 | 13-AUG-2015 H: 6815.10 L: 3740 | | | | 31-DEC-2020 | M: 12 D: 13 |
| 31 3109-001 Airframe PART #667 | FDR (ULB) UNDERWATER LOCATOR BEACON Part Number Serial Number 266-E0305-00 SD50270 Notes NEXT EXPIRE DATE DEC 2020 | 13-AUG-2015 H: 6815.10 L: 3740 | | | | 31-DEC-2020 | M: 12 D: 13 |
| 57 10-00-108 Airframe INSPECTION #1311 | DETAILED INSPECTION OF THE LOWER WING PLANK - FUEL DRAIN HOLE WS45.00, STRINGER 17 Reference Number AMM 57 10 00 220 837 | H: 0.00 | L: 4600 | | | L: 4600 | L: 386 |
| 57 10-00-124 Airframe INSPECTION #1321 | SPECIAL DETAILED INSPECTION OF LOWER WING PLANK-WS148 STRINGERS 8 TO 10 AND 15 Reference Number NDT ET-57-20-007 | 29-OCT-2010 H: 5027.10 L: 2905 | L: 1700 | | | L: 4605 | L: 391 |
| 24 23-25-101 Airframe PART - Life Limited #3345 | DISCARD OF THE AIR DRIVEN GENERATOR (ADG) UPLOCK ACTUATOR (SQUIB) (P/N 055046B) Part Number Serial Number 055046B 4966 Notes DOM: 8/2017 | 16-OCT-2017 H: 7438.60 L: 3990 | M: 42 | | M: 2 | 16-FEB-2021 | M: 13 D: 29 |





Maintenance Due List

N712PR

| ATA / Type / Group | Description | Compliance | Intervals | Tolerance | TSN/TSO | Next Due | Remaining |
|--|---|--------------------------------------|------------|-----------|---------|-------------|-------------|
| 26 00-KCA-9025 Airframe INSPECTION #308 | FIRE EXTINGUISHER (WATER TYPE) HYDROSTATIC TEST Part Number: 892-480 Serial Number: 722 | 24-AUG-2016 H: 7077.90 L: 3851 | M: 60 | | | 03-MAR-2021 | M: 14 D: 13 |
| | Notes NEXT DUE 03/2021 | | | | | | |
| 5 0030 Airframe INSPECTION #23 | CHECK 600 LANDINGS | 11-FEB-2019 L: 4116 | L: 600 | | | L: 4716 | L: 502 |
| 53 30-00-113 Airframe INSPECTION #1137 | DETAILED INSPECTION OF THE REAR PRESSURE BULKHEAD WEB FEED-THROUGH HOLES AND CUTOUTS Reference Number AMM 53 30 01 220 831 | 05-DEC-2011 H: 5559.40 L: 3229 | L: 1500 | | | L: 4729 | L: 515 |
| 5 0020 Airframe INSPECTION #3137 | 1200 HOUR CHECK | 24-AUG-2016 H: 7077.90 L: 3851 | H: 1200.00 | | | H: 8277.90 | H: 535.70 |
| 53 20-00-147 Airframe INSPECTION #1097 | DETAILED INSPECTION OF THE STOPS, FITTINGS AND ATTACHMENTS OF THE OVERWING EMERGENCY EXIT. Reference Number AMM 53 20 01 220 865 | 25-MAY-1996 H: 0.00 | L: 4750 | | | L: 4750 | L: 536 |
| 56 10-00-104 Airframe INSPECTION #1287 | SPECIAL DETAILED INSPECTION OF THE BOLTS AT THE WINDSHIELD AND SIDE WINDOW T-PLATES Reference Number NDT PT-56-10-001 | 13-OCT-2014 H: 6453.38 L: 3595 | L: 1200 | | | L: 4795 | L: 581 |
| 57 10-00-128 Airframe INSPECTION #1324 | SPECIAL DETAILED INSPECTION OF LOWER WING PLANK - WS163 STRINGER 15 Reference Number NDT ET-57-20-018 | 13-OCT-2014 H: 6453.38 L: 3595 | L: 1200 | | | L: 4795 | L: 581 |
| 57 70-00-101 Airframe INSPECTION #1389 | SPECIAL DETAILED INSPECTION OF THE FLIGHT SPOILER Reference Number NDT ET-57-70-001 | 13-OCT-2014 H: 6453.38 L: 3595 | L: 1200 | | | L: 4795 | L: 581 |





Maintenance Due List

18-Dec-2019

N712PR

| ATA / Type / Group | Description | Compliance | Intervals | Tolerance | TSN/TSO | Next Due | Remaining |
|---|---|--------------------------------------|-----------|-----------|---------|-------------|------------|
| 53 ZL-00-220 Airframe INSPECTION #1201 | GENERAL VISUAL INSPECTION FLIGHT COMPARTMENT EXTERNAL <small>Reference Number</small> AMM 53 10 01 210 811 | 22-JUL-2019 H: 7680.60 L: 4165 | M: 24 | | | 22-JUL-2021 | M: 19 D: 4 |
| 34 2201-001A Airframe INSPECTION #884 | STANDBY COMPASS 34-22-01-9001 CALIBRATION COMPASS SWING <small>Part Number</small> PAI-700 <small>Serial Number</small> 73739 | 25-JUL-2019 H: 7680.60 L: 4165 | M: 24 | | | 25-JUL-2021 | M: 19 D: 7 |
| 52 11-00-101 Airframe INSPECTION #1013 | SPECIAL DETAILED INSPECTION PASSENGER DOOR HINGE <small>Reference Number</small> NDT ET-52-10-001 | H: 0.00 | L: 5300 | | | L: 4800 | L: 586 |
| 53 20-00-123 Airframe INSPECTION #1080 | DETAILED INSPECTION OF THE STRINGER SPLICE - STRINGER 13, FS513 <small>Reference Number</small> AMM 53 20 01 220 844 | H: 0.00 | L: 4800 | | | L: 4800 | L: 586 |
| 53 20-00-126 Airframe INSPECTION #1082 | SPECIAL DETAILED INSPECTION OF THE KEEL LONGERON <small>Reference Number</small> NDT ET-53-20-002 | H: 0.00 | L: 5300 | | | L: 4800 | L: 586 |
| 55 20-00-103 Airframe INSPECTION #1245 | DETAILED INSPECTION OF THE ELEVATOR HINGE BOLTS <small>Reference Number</small> AMM 55 10 01 220 814 | H: 0.00 | L: 4800 | | | L: 4800 | L: 586 |
| 56 10-00-105 Airframe INSPECTION #1288 | SPECIAL DETAILED INSPECTION OF THE ATTACHMENT BOLTS FOR THE WINDSHIELD AND SIDE WINDOW <small>Reference Number</small> NDT PT-56-10-002 | H: 0.00 | L: 4800 | | | L: 4800 | L: 586 |
| 57 10-00-114 Airframe INSPECTION #1316 | SPECIAL DETAILED INSPECTION OF THE LOWER WING PLANK AT THE REAR SPAR - WS59 TO WS65 <small>Reference Number</small> NDT ET-57-20-019 | H: 0.00 | L: 5250 | | | L: 4800 | L: 586 |
| 57 10-00-148 Airframe INSPECTION #1335 | DETAILED INSPECTION OF WING UPPER SURFACE <small>Reference Number</small> AMM 57 10 00 220 857 | H: 0.00 | L: 4800 | | | L: 4800 | L: 586 |





Maintenance Due List

18-Dec-2019

N712PR

| ATA / Type / Group | Description | Compliance | Intervals | Tolerance | TSN/TSO | Next Due | Remaining |
|---|---|--------------------------------------|-----------|-----------|---------|-------------|-------------|
| 57 10-00-149 Airframe INSPECTION #1336 | DETAILED INSPECTION INTERNAL STRUCTURE OF THE WING BOX Reference Number AMM 57 10 00 220 858 | H: 0.00 | L: 4800 | | | L: 4800 | L: 586 |
| 57 30-00-101 Airframe INSPECTION #1352 | DETAILED INSPECTION EXTERNAL SURFACES OF THE WING TIP Reference Number AMM 57 30 00 220 802 | H: 0.00 | L: 4800 | | | L: 4800 | L: 586 |
| 57 50-00-108 Airframe INSPECTION #1361 | SPECIAL DETAILED INSPECTION OF INBOARD FLAP HINGE BOXES Reference Number NDT ET-57-50-001 | H: 0.00 | L: 5300 | | | L: 4800 | L: 586 |
| 57 60-00-103 Airframe INSPECTION #1388 | DETAILED INSPECTION OF THE HINGE BOLTS OF THE AILERON Reference Number AMM 57 60 01 220 807 | H: 0.00 | L: 4800 | | | L: 4800 | L: 586 |
| 57 70-00-103 Airframe INSPECTION #1391 | DETAILED INSPECTION OF THE HINGE BOLTS OF FLIGHT SPOILER Reference Number AMM 57 70 01 220 804 | H: 0.00 | L: 4800 | | | L: 4800 | L: 586 |
| 26 20-00-205 Airframe INSPECTION #349 | FUNCTIONAL TEST (WEIGHT CHECK) OF THE CABIN PORTABLE FIRE EXTINGUISHER CONTAINER Notes WEIGHT: 4LBS 18OZ | 16-JUL-2019 H: 7678.40 L: 4164 | M: 24 | | | 31-JUL-2021 | M: 19 D: 13 |
| 26 20-00-205 Airframe INSPECTION #345 | FUNCTIONAL TEST (WEIGHT CHECK) OF THE COCKPIT PORTABLE FIRE EXTINGUISHER CONTAINER Notes WEIGHT: 4LBS 16 OZ | 16-JUL-2019 H: 7678.40 L: 4164 | M: 24 | | | 31-JUL-2021 | M: 19 D: 13 |
| 27 00-00-206 Airframe INSPECTION #357 | DETAILED INSPECTION OF THE RUDDER AND ELEVATOR CONTROL CABLES IN THE AFT EQUIPMENT COMPARTMENT Reference Number AMM 27 00 00 220 806 | 22-JUL-2019 H: 7680.60 L: 4165 | M: 24 | | | 31-JUL-2021 | M: 19 D: 13 |





Maintenance Due List

18-Dec-2019

N712PR

| ATA / Type / Group | Description | Compliance | Intervals | Tolerance | TSN/TSO | Next Due | Remaining |
|--|---|--------------------------------------|------------|-----------|---------|-------------|-------------|
| 26 00-KCA-9027 Airframe INSPECTION #309 | FIRE EXTINGUISHER (WATER TYPE) FUNCTIONAL TEST Part Number: 892-480 Serial Number: 722 | 24-AUG-2016 H: 7077.90 L: 3851 | M: 60 | | | 24-AUG-2021 | M: 20 D: 6 |
| | Notes NEXT DUE 03/2021 | | | | | | |
| 53 10-00-104 Airframe INSPECTION #1039 | DETAILED INSPECTION WINDOW LOWER SILL - FS235, FS249 AND FS264 Reference Number AMM 53 10 01 220 817 | 13-JUN-2013 H: 5857.50 L: 3365 | L: 1500 | | | L: 4865 | L: 651 |
| 5 0017 Airframe INSPECTION #3 | 800 HOUR CHECK | 12-MAR-2019 H: 7610.30 L: 4123 | H: 800.00 | | | H: 8410.30 | H: 668.10 |
| 76 11-00-101 Airframe INSPECTION #1683 | FUNCTIONAL TEST OF THE ENGINE THROTTLE CONTROL GEARBOX, PART NO. 2100140-005 / -007. Reference Number AMM 76 11 13 720 802 | 18-JUL-2017 H: 7416.00 L: 3978 | H: 1000.00 | | | H: 8416.00 | H: 673.80 |
| 76 11-00-101 Airframe INSPECTION #1685 | FUNCTIONAL TEST OF THE ENGINE THROTTLE CONTROL GEARBOX, PART NO. 2100140-005 / -007. Reference Number AMM 76 11 13 720 802 | 18-JUL-2017 H: 7416.00 L: 3978 | H: 1000.00 | | | H: 8416.00 | H: 673.80 |
| 5 0018 APU 1 INSPECTION #16 | APU - 1200 HOUR CHECK | 24-AUG-2016 H: 5374.00 | H: 1200.00 | | | H: 6574.00 | H: 682.00 |
| 57 10-00-117 Airframe INSPECTION #1318 | SPECIAL DETAILED INSPECTION OF LOWER WING PLANK WS85.5, STRINGERS 14 TO 17 Reference Number NDT ET-57-20-017 | 26-FEB-2019 L: 4123 | L: 850 | | | L: 4973 | L: 759 |
| | Notes NDT inspection performed with no defects noted | | | | | | |
| 52 31-00-203 Airframe INSPECTION #1024 | DETAILED INSPECTION INTERNAL STRUCTURE OF THE CARGO COMPARTMENT DOOR Reference Number AMM 52 31 01 220 803 | 16-JAN-2018 H: 7440.00 L: 3992 | M: 48 | | | 16-JAN-2022 | M: 24 D: 29 |





Maintenance Due List

18-Dec-2019

N712PR

| ATA / Type / Group | Description | Compliance | Intervals | Tolerance | TSN/TSO | Next Due | Remaining |
|--|---|-------------|-----------|-----------|---------|-------------|-------------|
| AD 2017-19-06 AMD 39 -19036 Airframe AD - Recurring FAA #3352 | TO PREVENT THE LOSS OF STRUCTURAL INTEGRITY OF THE SIDE BRACE FITTING SHAFT AND SIDE BRACE-TO-AIRPLANE FITTING PIN OF THE MLG (EFFECTIVE 27 OCTOBER 2017) | 16-JAN-2018 | M: 48 | | | 16-JAN-2022 | M: 24 D: 29 |
| | Notes AD 2017-19-06 SIDE BRACE FITTING SHAFT AND SIDE BRACE-TO-AIRPLANE FITTING PIN: COMPLIED WITH PARAGRAPH (g) OF THIS AD, PARAGRAPH (h) DUE IN 48 MONTHS | | | | | | |
| AD 2018-20-21 AMD 39 -19455 Airframe AD - Open FAA #3462 | TO ADDRESS FLUID ENTERING THE COCKPIT FLOODLIGHT FIXTURES (EFFECTIVE 20 NOVEMBER 2018) | | | | | 20-JAN-2022 | M: 25 D: 2 |

